

# ***Checklist after service of PLM***

*PLM 20000Q*

***Created by: PT***

***Date: 2013-01-08***

---

## **Index**

<b>1</b>	<b>INTRODUCTION .....</b>	<b>2</b>
<b>2</b>	<b>CHECK LIST PLM-SERIES .....</b>	<b>2</b>


## **1 Introduction**

This checklist shall be used to make sure the amplifier is always checked in a proper way after service has been done. It is important to follow the steps in this check list and check all points so that the set up of parameters in the amplifier is correct adjusted. When have done all checks and adjusted the parameters the amplifier will work properly and will have the output power that it is designed for.


## **2 Check list PLM-series**

Always clean the amplifier by blowing with compressed air through coolers and fans. Be careful when blowing where big electrolytic capacitors are placed so that the capacitor doesn't get damaged.


1.	SECONDARY GROUND. <b>SG</b>	
----	-----------------------------	--




2.	PRIMARY POWER GROUND. <b>PPG</b>	
----	----------------------------------	--




3.	Ensure fuses are mounted and working.	20A250V
----	---------------------------------------	---------




4. Ensure that potentiometer PSMCU is in min-position.




**Alternative potentiometer**



5. Mount safe-mode jumper.




6. Ensure that Trimmer Resistor RAIL is in min-position (clockwise from solder side).




7. Attach multimeter for RAIL and use **SG** for reference (**Pic 1**).  
Attach multimeter to PFC-voltage and use **PPG** (**Pic 2**).  
Attach 1:100probe and earth clip for oscilloscope in **PPG**  
**Note! Use an isolation transformer for the oscilloscope (Pic3).**


**Pic 1**




**Pic 2**



**Pic 3**






**OVERVIEW**




- |    |  |
|----|--|
| 8. | Plug in power cord, signal cables and network cable. Network cable in secondary port.  |
| 9. | Ramp up variable voltage transformer to 110VAC. Start the amplifier on the power button.<br>Multimeter RAIL ~ 1-5VDC<br>Multimeter PFC ~22-26VDC |


10. Measure 6 switch nodes with 1:100-probe grounded in PPG. Important that the wave is symmetrical.




11. New oscilloscope settings.



12. Slowly ramp up PFC voltage with potentiometer on PSMCU to max (~220VDC)




**Alternative potentiometer**







13. Slowly ramp up RAIL voltage to 200VDC +/-0,5VDC. (counter clockwise)



14. The wave should be slightly angled.




15. If the performed tests have worked according to instruction, turn off the amplifier with the variable voltage transformer 0VAC.  
Remove the safe-mode jumper.


16. Ramp up variable voltage transformer to anywhere between 110 and 230 VAC.

17. RAIL-voltage 200VDC +/-0,5VDC. PFC-voltage ~380VDC

18. Measure 6 switchnodes with 1:100-probe grounded to **primary power ground (PPG)** according to earlier picture. In this measurement the output modules are active and the power supply is running with load. The wave in pic **A** is now slightly angled, if the wave is straight something is wrong and the power supply will go hot. The break in the wave on pic **B** can occur on slightly different levels.



**PicA**



**PicB**

19. Check output signal from one channel at a time by activating mute on the remaining channels.


20. Press MUTE ENABLE. The text flashes.




21. Red diode indicates muted channel. Green diode indicates channel active.



22.	<p>When testing a channel; Check so that you get two bars on the user interface also check so that the channel goes into voltage clip.</p> <p>Check offset with no input (+/- 50mV). Increase input signal and check output signal at clip 8Ω</p>		
-----	---	--	--




Wave measured at 1.3kHz.



Wave measured at 13kHz.

23.	<p>When all channels have been tested activate all outputs and inputs. Power down with power-button.</p>		
24.	<p><b>Turn down the variable voltage transformer to 0VAC!</b></p>		
25.	<p><b><u>Safety precaution!</u></b> Use a 56Ω10w resistor to discharge the stored energy in the capacitors.</p>		



---

26.	Check dust filters, change when needed.		
-----	---	--	--