Page 1 of 11

Page:

## **Technical Service Bulletin No. 23**

## Created by: Lab.gruppen AB Service Department Date: 2011-11-02

Reference no: Measure for broken NTC in DC/DC on SP200PCF

It is highly recommended to implement this service bulletin as preventative maintenance if the unit is serviced for another issue.

### Affected models

PLM20000Q

### Affected boards/modules

Describe which boards/modules this technical issue affects.

SP200PFC07e-F01 SP200PFC08a-F01 SP200PFC08c-F01 SP200PFC08d-F01 SP200PFC08e-F01 SP200PFC08f-F01 SP200PFC08g-F01 SP200PFC08h-F01 SP200PFC08i-F01 SP200PFC08j-F01 SP200PFC08k-F01 SP200PFC081-F01 SP200PFC09b-F01 SP200PFC09c-F01 SP200PFC09e-F01 SP200PFC09g-F01 SP200PFC09h-F01

## **Symptom**

Firmware will tolerate 1 out of the 3 NTC in the DC/DC to be broken without displaying a fault message, that's why all three NTC's need to be measured every time the unit is in for service.

If more than 1 NTC in the DC/DC is broken, or if any of the other NTC's are broken (there is a total of 7 on SP200PFC), the following fault message will be displayed on the front panel of the PLM: "*NEED SERVICE:6*"

LAB.GRUPPEN	
NNOVATIVE POWER SOLUTIONS	Document type:

SERVICE BULLETIN (2014-04-08)

Created:

## Solution

Ohm measure NTC601, NTC702 and NTC802. If outside ~18-20kOhm at room temperature, the NTC need to be replaced.

## Instructions


### Needed material

Part No.	Description	Amount	Info	Pos
NTC100KPEFILM	Resistor Ntc 100k Pe Film	1 - 3	Measure	NTC601, NTC702,
				NTC802
ISSR28x15AD	Insulator Silicon Rubber 28x15mm Adhesive	1 - 3		On Cooler
TSK.075x12	Tape Selfadhesive Kapton 0.075x12mm			Таре

Actions		Info	Pos
1.	Amplifier mains plug disconnected.		
	Wait 10 minutes in order to let the capacitors discharge.		
	<b>Observe! Do not touch PCB without being ESD-protected.</b>		




2. Remove screws from the rear panel.



LAB.GRL	IDDENI

#### Page: Page 3 of 11


## 3. Remove screws from the side panels.



4. Remove screws from the top and bottom covers. Remove the covers.




5.At room temperature, **Ohm measure**;<br/>NTC601, NTC702, NTC802~18kOhm to<br/>~20kOhm





Overview SP200 of which region of the board.

Page: Page 4 of 11



Example OK measurement of NIC702 on a **Rev8** SP200





LAB.GRUPPEN	l
	ł

Document type:	Created:
SERVICE BULLETIN	(2014-04-08)

Page: Page 5 of 11

6. If any of NTC601, NTC702, NTC802 does **not** pass ~18-20kOhm at room temperature, this NTC needs to be exchanged.

# 1.1 The following is an example on how to exchange NTC702 (exactly the same for NTC601 or NTC802 on either side).

7.	Remove laminate.	





LAB.GRUPPEN
INNOVATIVE POWER SOLUTIONS

Document type: Created: SERVICE BULLETIN (2014-04-08) Page: Page 6 of 11


8.	Use a flat screwdriver.	

# 9. Put it behind the clip and the aluminum cooler, and bend carefully.






Page: Page 7 of 11



LAB.GRUPPEN
INNOVATIVE POWER SOLUTIONS

Document type:	Created:	Page:
SERVICE BULLETIN	(2014-04-08)	Page 8 of 11


10.	Now the NTC is free, and can be exchanged if needed. The NTC shall be soldered straight so it can be placed flat against the cooler. Put the PLM on the side, so that you can heat on the backside of the PCB and pull out the NTC at the same time.	
	Confirm that the exchange NTC is OK. <u>Unmounted</u> and in room-temperature it shall <u>measure ~100kOhm</u> (due to lack of biasing).	




<b>LAB.</b> GRUPPEN
INNERVATIVE DOWER SOLUTIONS.

Document type:	Created:	Page:
SERVICE BULLETIN	(2014-04-08)	Page 9 of 11

11.	Mount the adhesive silicone sheet on the cooler where the	
	NTC is going to be mounted (fold around edge).	




12.		NTC
	Place the NTC resistor against silicon sheet.	




Page: Page 10 of 11

Tape


## 13. Mount specified tape to fixate the NTC.




1	14.	Observe that the clip needs to be mounted with the soft side		1
		towards the NTC.		1



## 15. Assemble clip on this side with the foam first.



16. Then the other side.



17. Reverse actions 5-6 and 4 to 2.
-------------------------------------

## Service repair report forms

Write "Technical Service Bulletin no.23" in the service repair report form, column "Repair Remedy" besides other normal repair information.

## History

Date	Created By	Status	Bulletin no.	Comment
20111102	DABER	OLD	23	
20140408	ALRIQ	SHARP	23	Service repair report form information added