

Service Note		
Product	Description:	Service note no.
Nova Repeater	Distortion and oscillation	SNo-T0110

Reason for note:

Analog delay type will distort and oscillate when tapping delay times over 1200ms

Actions:

Load software version 1.01 (or newer)

IMPORTANT:

This replacement should only be carried out by skilled technicians.