

Service Note		
Product	Description:	Service note no.
RebelStack	Replacement of HF and LF driver	SNo-T0109

Reason for note:

The threads in between the Coax Driver and the HF driver are in production glued together to avoid that the HF driver shakes loose during use. Experiences have shown that it is very difficult to disassemble the drivers from each other. This means that it can be necessary to replace both drivers if one of them is defect.

Actions:

If these drivers has been disassembled or replaced it is necessary to glue them together again and for this we recommend to use Loctite Threadlocker 2400 or 2700, or equivalent.

IMPORTANT:

This replacement should only be carried out by skilled technicians.