Service Note		
Product	Description:	Service note no.
TC2290	Updating SA02 To FATR/STSA:	706 10 T070

IMPORTANT: In connection with FATR/STSA-options in the 2290 C4 on the SA02option must be 4,7 uf/ min.10V (only SA02 options with s.no. lower then 960130).

If SA02-option that is to be used has s.no. higher than 960130 there are mounted a 22 uF electrolytic-capacitor on the solder side of the SA02-option. This capacitor has to be cut out.

Filename: SNo_T070.doc Date: 11-04-2007

ID:Thsig