

Service Note		
Product	Description:	Service note no.
BM5A Compact	Abnormal humming sound	SNo-T0155


Reason for note:

In standby mode is for some speakers detected a significant abnormal humming sound which is caused by the transformer.

The speakers that are potentially affected can be visually dissociated in "Good" and "Bad ". This is illustrated below:



The correct transformer can also be readily identified that there is a round and green "QC Passed" label and a white label with printed production date (see picture below).



Actions:

Please handle as standard repairs if you get any complaints.

IMPORTANT:

This repair should only be carried out by skilled technicians.