


Service Note		
Product	Description:	Service note no.
BM5A BM5A Comp. BM6A MK II BM12A	Bad connection in signal cable	SNo_T095

Reason for note: Recently it has been discovered that there can be a bad connection in the signal cable going from the input board to the amp board.

Actions: Wires shall be soldered directly in the PCB's.



IMPORTANT: This shall be carried out on all modules that come in for service.

This replacement should only be carried out by skilled technicians.