Service Note		
Product	Description:	Service note no.
TC Helicon products with software upload possibility	Firmware download from Voicesupport	SNo-T0153

Reason for note:

When using TC Helicons Voicesupport for downloading new firmware it happens that an error occurs.

After a failed attempt the unit intended for the firmware can get into a deadlock, where a new attempt is not possible.

Actions:

There is a possibility to access the unit by using MIDI to update.

Please follow advises from the Techsite and if you do not succeed please contact Music support.

IMPORTANT: N/A