Service Note		
Product	Description:	Service note no.
BG500 - BH500	Transformer being loose	SNo-T0175

Reason for note:

We have seen cases where the washer breaks resulting in the nut coming of as well as resulting in the transformer being loose.

Actions:

Cure is to replace the 4 nuts and washers with serrated nuts. Part number for a serrated nut is 7E56400911. This must be done for all products coming in for service.

The old solution with nut and washer.
The new solution with a serrated nut.



IMPORTANT:

N/A