

<b>Service Note</b>		
Product	Description:	Service note no.
<b>RH750</b>	<b>Noise from fan</b>	<b>SNo-T203</b>

### **Reason for note:**

New firmware is released and is available on this site.

Tests have shown that we can reduce the fan speed without getting any unwanted impact in any critical circuits of the amplifier. A reduced fan speed introduces less noise and that is the reason for this firmware release.

### **Actions:**

If a RH750 comes in for service and the customer complains about the noise from the fan, updating the firmware may be the solution.

If the firmware is updated for other reasons it might be wise to inform the customer afterwards about the change in fan speed, as he could think that his unit was malfunctioning.

### **IMPORTANT:**

Please handle this as a standard repair.