

Service Note		
Product	Description:	Service note no.
VoiceTone Create XT	Forced front AVR update Might be necessary after replacement of either UI board or main board	SNo-T0130

Reason for note:

After replacement of either UI board or main board there might be a mismatch in software between these boards. Before the unit is able to boot up it might be necessary to force an AVR update

Actions:

To force an AVR update hold down both footswitches and the "Tweak" button on power up. This forces the AVR to update to the version which is contained on the pre-programmed flash.

IMPORTANT:

This repair should only be carried out by skilled technicians.