

Service Note		
Product	Description:	Service note no.
VoiceTone Harmony G XT	Forced front AVR update Might be necessary after replacement of either UI board or main board	SNo-T0131

Reason for note:

After replacement of either UI board or main board there might be a mismatch in software between these boards. Before the unit is able to boot up it might be necessary to force an AVR update

Actions:

To force an AVR update hold down both footswitches and the “Voice 2” button on power up. This forces the AVR to update to the version which is contained on the pre-programmed flash.

IMPORTANT:

This repair should only be carried out by skilled technicians.