

Service Note		
Product	Description:	Service note no.
VoiceLive	Intermittent freezing and Mix pots problem.	SNo-T0125

Reason for note:

Software version 1.32 has been released

This software impliments two changes over previous production software.

1. A fix which helps prevent freezing in some units.
2. Lower sensitivity on 4 mix pots which helps prevent product from entering mix screen when not desired.

Actions:

Update to software version 1.32 (or newer) which is now available from Tech server site

IMPORTANT: