2018-05-17



# Technical Service Tip SCBA-XXX

Created by: Music Tribe Brands Sweden AB Service Department

Date: 2018/05/17

Reference no: SCBA-01Ab

## Affected models

Following models are affected by this service tip: IPD2400

#### Affected boards/modules

SCBA-01Ab

### **Symptom**

Customer can experience loss of gain and/or loss of the units presets

### Solution


Replacement of the SCBA-XXX board




### Instructions

Instructions on how to replace the SCBA-XXX board.

Start by removing the top cover




Remove the connectors shown with the pink arrows from the SCBA-XXX board






# Remove the connector shown with the orange arrow placed on the SCBA-XXX board




#### Remove the two fan connectors









Remove the screws from the SCBA-XXX shown with the pink arrows, then remove the SCBA-XXX and mount the new SCBA-01Ab

