

# ***Technical Service Bulletin No. 33***

***Created by: Lab.gruppen AB Service Department***

***Date: 2013-02-08***

***Reference no: Ejected pins***

---

## ***Affected models***

---

Following models are affected by this technical service bulletin:

C 5:4X

C 10:4X

C 10:8X

C 20:8X

## ***Affected boards/modules***

---

SP20FXXX-XXX

## ***Symptom***

---



The PCB pins jump out of their slot on the front panel during transport. See pictures below.

## ***Solution***

---

If this has occurred, the SP20FXXX-XXX needs to be replaced, because we can't guarantee that it has not been damaged.

### Examples of what it might look like.



## **Service repair report forms**

Write “Technical Service Bulletin no.33” in the service repair report form, column “Repair Remedy” besides other normal repair information.

### **History**

Date	Created By	Status	Bulletin no.	Comment
2013-02-08	PT	OLD	33	
20140408	ALRIQ	Sharp	33	Service repair form information added