

Service Note		
Products	Description:	Service note no.
DB-max, D22, P2	Cut outs in alu foil on top cover	720101810

Reason for note

IMPORTANT:

This replacement should only be carried out by skilled technicians.

Symptoms:

Due to observations with short circuits at IC pins caused by a chip of the aluminium foil which is stuck on the top cover of the above mentioned 3 Wizard products, we had to make a change in our production.

When products comes in for service they need to be checked for(including the cover) loose alu chips.

Procedure:

Make cut outs in the foil where the screws come through the top cover. That must be done before the foil is stuck to the top cover according to the enclosed drawing.

Thereby the small alu chips which have caused short circuits should be eliminated.

Top cover with stuck on alu foil, with the nescessary cut outs

