

Service Note		
Product	Description:	Service note no.
M2000	Software changes M2000 2.06	720 10 T041

The latest software version is 2.06

Software changes from 2.05 to 2.06:

1. MIDI-clock-tracking at TAP-stock does not work. Fixed.
2. Power On button should be un-pressed before powerdown. Corrected.

Software changes from 2.04 to 2.05:

There was no CRC generated on AES output when in AES mode. Corrected.
Software changes from 2.03 to 2.04:

ASIC-related noise in delay-algorithm removed.
Software changes from 2.02 to 2.03:

When a Rev-3 preset is selected (e.g. #1) Engine 2's left output isn't muted when set in Dual Mono or Stereo Routing mode, causing signal on both left and right output even with signal on Right input only. - Corrected.

You can download the latest software below.

NOTICE !! This software is only for M2000 with S/N higher than 1110000