

Service Note		
Product	Description:	Service note no.
VoiceLive 3	Guitar input path noise reduction	SNo-T0189

Reason for note:

We have experienced malfunction in the guitar input path noise reduction circuitry on some of the first VoiceLive 3's manufactured..

Actions:

To eliminate this problem we urge you to replace the footswitch boards on all VoiceLive 3's in for service if these are version P22674-**BAA**. They must be replaced with P22674-**CAA** (or in the future maybe newer versions)

The version code is to be found here



The footswitch PCBA board (with footswitches mounted) can be ordered from TC. Please remember you need 2 boards for one VoiceLive 3.

Part number is 7F85613099, Voicelive 3 PCBA P22674 Foot-SW with footswitches

IMPORTANT:

This repair should only be carried out by skilled technicians.

Please handle this as a standard repair