

Service Note		
Product	Description:	Service note no.
TC1280	Hum problem	705 10 03 01

IMPORTANT:

Modification should only be carried out by skilled technicians.
This note concerns units with serial no. lower than 120100.

Symptoms before modification:

Hum at a very low level at the outputs.

We have noticed that under special circumstances This problem is due to the screw holding the transformer istouching the top cover. So to cope with this problem in theeasiest way for you (and us) we will ask you to do thefollowing simple action to solve the problem.

Procedure:

1. **Turn Off Power And Disconnect Power Cord.**
2. Dismount the top lid.
3. Locate the transformer
4. Place the piece of plastic supplied with this letter on top of the transformer(double adhesive tape).
5. Mount the top lid.
6. Connect power cord and turn on power.