

<b>Service Note</b>		
Product	Description:	Service note no.
<b>VoiceTone Synth</b>	<b>Forced front AVR update</b>  Might be necessary after replacement of either UI board or main board	<b>SNo-T0129</b>

**Reason for note:**

After replacement of either UI board or main board there might be a mismatch in software between these boards. Before the unit is able to boot up it might be necessary to force an AVR update

**Actions:**

To force an AVR update hold down both footswitches and the "Trans" button on power up. This forces the AVR to update to the version which is contained on the pre-programmed flash.

**IMPORTANT:**

This repair should only be carried out by skilled technicians.