

# Technical Service Bulletin No. 39

**Created by: Lab.gruppen AB Service Department**

**Date: 2015-10-08**

**Reference no: Firmware update A-LP4A4D**

## Affected models

Following models are affected by this technical service bulletin:

PLM+

D-Series Lake

## Affected boards/modules

A-LP4A4D

## Symptom

The unit could have problem to start up because of software issues

## Solution

Upgrade to latest firmware with the solutions below

Upgrade of the Flash Memory ECC Correction Functionality

**V6.4.2 includes an upgrade of the flash memory ECC correction functionality that will increase the lifetime of internal memory of PLM+ and D Series amplifiers. We urge all users of these models to upgrade at their earliest convenience to ensure optimum reliability.**

***This issue does not regard the previous PLM range or the LM Processor***

## Service repair report forms

**Write “Technical Service Bulletin no.29” in the service repair report form, column “Repair Remedy” besides other normal repair information.**

## History

Date	Created By	Status	Bulletin no.	Comment
2015-10-09	AR	Sharp	39	