	Service Note		
Product	Description:		Service note no.
M2000	**Software changes m2000 1.10**		**720 10 T040**

The latest software for the M2000 MKI is version 1.10.

NOTICE !! This is for all M2000 with a S/N lower than 1110000.

You can download the software below.

Software changes from 1.09 to 1.10 :

- Chorus, Flanger, Tremolo, Phaser are now under the "CHO" category.
- EQ, Spatial Expand are now under the "MIS" category.
- Pitch Edit text added : "Voice (1-6)"
- Delay in Chorus and Flanger now shown in "ms" instead of samples.
- Preset Compatible, old user presets sound the same.
- Tuner now has big arrow and tuning guides as in manual.
- In Stereo Routing the Combined Recall display did not always show the correct default parameter and algorithm. Now fixed.
- Combined Recall Preset 4, edit engine 1, Combined Recall does not show edited. Now fixed.
- In Stereo Routing Combined Edit the two levels now follow each other.
- Digi IN->OUT gain in bypass fixed. AD error compensation, -2dB before AD +2dB after.

Software changes from 1.08 to 1.09 :

- pedal tap didn't work. Now fixed
- security lock implemented
- automatic re-initialization of the display implemented

Filename:
SNo_T040.doc
Date: 03-01-2007
ID:Thsig

TC Electronic

Page 1 of 1

Service-Level | L1