Service Note

Product	Description:	Service note no.
Icon Remote MKl	**Compact Flash boot fail**	**SNo-T0139**

Reason for note:

When upgrading or replacing a defective CF card from an Icon hardware MKI, you might have had a 64Mb CF card in the machine and you are now replacing it with a 1 GB CF card.

When booting for the first time you get a "Invalid or damaged bootable partition"
This is due to an old bios function called "IDE HDD AUTO DETECTION" that has to be run.

Actions:

Reboot the machine and press DEL to enter BIOS….password is ICON.

Go to the IDE HDD AUTO DETECTION and press ENTER.
Then press ENTER 2 times
And on secondary Master press 2 and ENTER.
Then press F10 and Y and the systems reboots and is now able to see the new CF card.

IMPORTANT: