DBM50 PSU bottom placement

Revision A