

Service Note		
Product	Description:	Service note no.
Polytune Different pedals	Battery sometimes discharges too quickly	SNo-T0149

Reason for note:

We have experienced that some enclosed batteries discharges too quickly.

Actions:

Please check battery functionality before possible return or scrap of the unit.

IMPORTANT: