Service Note		
Product	Description:	Service note no.
M6000	Replacing CPU + Ethernet board	712 10 T045

## **IMPORTANT:**

Modification should only be carried out by authorized technicians. CPU board and Ethernet board must always be replaced as a pair.

## **Procedure:**

- 1. Turn off power and disconnect power cord
- 2. Remove the lids.
- 3. Dismount the CPU board and Ethernet board as a pair.
- 4. Mount the new CPU board and Ethernet board as a pair
- 5. Delete serial number, remove battery for 30 seconds
- 6. Reinstall boot
- 7. Reset mainframe with .ctl file
- 8. Find code and send to TC service
- 9. Enter new code received from TC service

Filename: SNo\_T045.doc Date: 14-01-2007

ID:Thsig