

Service Bulletin

Date Issued	05 April 2001
Products Covered	VoicePrism serial number < 7002251
Issue	SNR performance can be reduced as low as 95db with version P1.03 application software and A3.06 DSP software.
Description	<p>R142, R144, and R146 can be removed on units with serial numbers less than 7002251 that have been upgraded to the above referenced software versions to restore SNR performance. This change is optional.</p> <p>VoicePrism units with serial numbers less than 7002251 are affected. Units with serial numbers greater than this have been modified by ECO1264</p>

Details:





illustration of R142,R144, R146 on main board PDC0147

TC Electronic A/S
Sindalsvej 34
DK-8240 Risskov
Denmark

Phone: +45 8742 7000 Fax: +45 8742 7010 E-Mail: www.service@tcelectronic.com
www.tc-helicon.com



location of R142,R144, R146 on main board PDC0147