

TCCode	Description	used pcs.
<b>Front section</b>		
720052011	Encoder+nut for Wizards	1
589017011	R2057-05 Nut for encoder Wizard	1
338056011	R2040-1 Plasticknob for Encoder Black Circular Diameter 30mm. <i>Please note that the knob today is without a nut inside.</i>	1
720013511	DBMAX II Front service PCB-set PC12502-3	1
336050011	LCD display Backlight=LED Pickvue PC071CYL Display for Wizard	1
340019111	ALPS Mini Switch SKHUAD 6 x 6mm, 2,5mm High, 1,56 Newton,G-Forc	19
338051511	R2031G-2 Plasticknob Black,Ral no.: 9017 3,81x7,62, DBMax, Gold Channel	9
338053011	R2033G-2 Plasticknob Grey for LED 3.81x17.78,Ral no.: 7011,M2000,Finalizer	1
338053211	R2033G-2 Plasticknob Black for LED 3,81x17,78, Ral no.: 9017	9
338055011	R2034-1 Light Guide for knob R2033 M2000,Finalizer,DBMax,...	10
<b>Chassis</b>		
584003012	R2011-05 Lid for Wizard 1.2.4.5.6.7	1
586000111	R2005-01 Profil Sideplate (Color: AG2), Color: AG2	2
<b>Main board</b>		
720013411	DBMAX II Main Service-PCB, v. 13006-x	1
720011132	PLL service PCB P12903-x (With SRC), *: See below	1
720011135	PLL service PCB P12903-x (With SRC), *: See below	1
434045011	8 MBit Flash 70nS TSOP/48P (Use only AMD and Fujitsu)	1
483005011	Asic "DARC 3", MHS/TEMIC QFP166 (Discontinued)	1
483001011	AD8403AR10 Digital Potentiometer SO24	1
491011011	AK5392-VS - 24 BIT AD CONVERTER SOP28	1
490005511	DSP XC56303PV100 144TQFP MaskRev: 0K36A	1
491009011	AK4324-VF DAC - 24 BIT D/A CONV. VSOP24	1
342000011	LITHIUM BAT.. 3V/200mA. CR2032RV (Diameter 20mm x 3.2mm)	1
522027011	J/SKT S4/BBB BK PC-C GLD Jack	1
522042011	RCA/Phono Double for PCB	1
567022011	PSTE-3-01 Spacer Plastic	2
<b>Power Supply</b>		
720060011	Wizard power supply	1
<b>Miscellaneous</b>		
E54700202	Cable U.S.A. Black 3x18 AWG SVT 180 cm.	
E54700102	Cable EU Europe Black 3x0.75mm H05VV-F 180 cm	
720070311	PCMCIA card w/ software for DBMAX	
611012011	Memorycard S-RAM 512KB	

\*: If the mainboard is the older type with DARC3 or it is a FGPA type with FPGA kode 2.9, 2.9a or 2A you must order a 720011132 PLL if you need one for service. Is it a newer mainboard with FPGA code 2B you need to order a 720011135 PLL board for service