Service Note		
Product	Description:	Service note no.
Nova System	Main board with/without S/PDIF	SNo-T0188

Reason for note:

Nova System and Nova System Limited Mainboard with S/PDIF" is not available any more.

Nova System and Nova System Limited Mainboard without S/PDIF" is still available.

Actions:


Before ordering for a Nova System which used to have S/PDIF, please advice the customer about this issue. Alternative repair the board or ship the Nova System to TC DK for repair.

All spare part main boards for Nova System comes in the future with a small sticker.

If the spare part board is for a Nova System born without S/PDIF you just disregard the sticker.

If the spare part board is for a Nova System born with S/PDIF you use the sticker to cover the holes in the cabinet where the S/PDIF connector was located.

Nova System board without S/PDIF connector:



Sticker to cover holes in cabinet where S/PDIF connector earlier was.

IMPORTANT:

N/A