

Service Note		
Product	Description:	Service note no.
Voice Live	Freeze of product after a few minutes use	Sno- T088

Reason for note:

Unfortunately we found out that there are products that freeze after a short period of use.

Actions:

Upload the latest software (V.1.31) provided in the tech. server and have the unit under surveillance for 24 hours.

IMPORTANT:

This replacement should only be carried out by skilled technicians.