

TANNOY®


DEFINITION DC10A

DUAL CONCENTRIC
ALNICO DRIVER
TYPE 2542
7900 1340

HF DIAPHRAGM
+ TRIM
7900 1347

RECONE KIT+TRIM
TYPE 2523
7900 1346

GRILLE ASSEMBLY
7900 1108



SPARE PARTS TO BE
PURCHASED
LOOSE FROM SUPPLIER ON
AD HOC BASIS:

PLINTH SPIKE – 4540 0027
LOCK NUT – 4825 0155
SPIKE CUP – 6165 0009

ISSUE 1 – 08.06.12

NOTE: IF REPLACING DUAL
CONCENTRIC DRIVER,
HF DIAPHRAGM OR
RECONE KIT, AN ADDITIONAL
TRIM KIT MUST BE PURCHASED
AS ORIGINAL TRIM WILL BE
DAMAGED ON REMOVAL.