

Service Note		
Product	Description:	Service note no.
S6k MKI, S6k MKII, DB4 and DB8	Change of diodes in PSU	SNo-T0127

Reason for note:

Diode D3 and D4 can in certain situations “burn” and stop the frame from starting up. In order to fix this new diodes with higher voltage must replace the old type.

Actions:

New diodes are implemented in TC production from the following serial numbers:

S6k: 289638

DB4: 292250

DB8: 292209

Frames with a lower serialnumber must be checked for type of diodes and diodes changed if old type.

The new diodes are Schottky, 16A, 150V, and can be ordered from TC using stock number 310022011

IMPORTANT:

This repair should only be carried out by skilled technicians.