

Service Note		
Product	Description:	Service note no.
VoiceTone Singles	Potentiometer Calibration	SNo-T0137

Reason for note:

When you've exchanged potmeters or UI board in a VoiceTone Single product you should re-calibrate the units as the new pots have a new taper.

Actions:

To re-calibrate the potentiometers you hold down the footswitch and re-power the unit 3 times. It will power up in pot calibration mode. From there the pots are calibrated left to right.

The process is:

Pot in its minimum position -> press footswitch
 Pot in its maximum position -> press footswitch
 Next pot
 Repeat

Once you've done all the pots wait for 30 seconds and re-power the unit.

IMPORTANT: