Service Note		
Product	Description:	Service note no.
RH450, RH750, Combo450, Staccato '51, Blacksmith	New improved knobs	SNo-T0191

## Reason for note:

Due to poor durability we have designed a new and better knob for the mentioned products.

The part number is still: 7E33806413, "DR09801-F, Plastic knob for Encoder" and for a package with 10 pieces: 7E33806499, "10 pcs DR09801-F, Plastic knob for Encoder"

All old knobs have been scrapped and all orders for knobs executed after August the 6<sup>th</sup>, 2014 will be the new improved type.

## **Actions:**

We recommend to replace old type of knobs on products coming in for service.