

Restriction nr1**1. This restriction concerns****COAEXPFC70-A01a****COAEXPFC70-A02a and COAEXPFC70-A02b****COCIPI4x2-A01a and COCIPI4x2-A01b****2. The SP200PFC board comes with coolers that have mounted components. Some of these coolers have compatibility problems. Below you can see how to find and replace the right type of cooler****3. The COAEXPFC70-A02 cooler should have a sticker, as you can see in the picture below. You can find 2 different types of coolers.****COAEXPFC70-A02a as you can see in PIC1 and COAEXPFC70-A02b****Make sure that the spare have the same item name as the original mounted cooler**

PIC1

**4. The COAEXPFC70-A03 cooler should have a sticker, as you can see in the picture below. You can find 2 different types of this cooler.****COAEXPFC70-A03a as you can see in PIC2 and COAEXPFC70-A03b****Make sure that the spare part has the same item name as the original mounted cooler.**

PIC2



- 5. The COCIPI4x2-A01 cooler should have a sticker, as you can see in PIC3 below. You can find 2 different types of this cooler. COCIPI4x2-A01a as you can see in PIC3 and COCIPI4x2-A01b. Make sure that the spare part has the same item name as the original mounted cooler**

PIC 3



If you don't find any stickers on the coolers, and you can't figure out what spare part to use. Replace all the coolers