

Clarity X spare part list

| TC order no: | Partname. | service level | | |
|-------------------------------|--|---------------|---|---|
| | | 1 | 2 | 3 |
| Main & SDI | | | | |
| | No spares are available for Main and SDI boards (transmission 3G), nor MADI however these can of course be send to MUSIC Group Research UK LTD for repair. New complete finished goods can be purchased: Transmission 3G Retrofit. Please contact TC sales | | | |
| AES Bal. Board | | | | |
| 712307071 | Service DSUB, AES BAL, P56084-A for Clarity X | | x | x |
| 7E50500711 | Relay, DPDT, single-side stable model | | | x |
| Analog Board | | | | |
| 712307091 | Service Analog, P56085-A board for Clarity X | | x | x |
| Remote Board | | | | |
| 712070172 | Service remote PCBA for Clarity | | x | x |
| Front | | | | |
| 712307191 | Service Clarity front profile with lightguide | | x | x |
| 712070171 | Service front PCBA for Clarity | | x | x |
| Power supply | | | | |
| 712062011 | Power Supply board ver.3, 5502-3 | | x | x |
| Miscellaneous | | | | |
| 7E54400111 | Ribbon cable 30 pol 100mm | | x | x |
| E58132512 | DR10154-B, 1315, Clarity remote, Encoder knob, S10159-A01 | x | x | x |
| E57609011 | DR10155-A, 1315, Houston remote, Rubber foot 2mm | x | x | x |
| E57609111 | DR10156-A, 1315, Houston remote, Rubber foot 3mm | x | x | x |
| 338053611 | R2033G-2 Plasticknob Grey for LED | x | x | x |
| E58117913 | DR08005-D topplate + silkscreen for DB6 | x | x | x |
| 544060011 | CPU6000 COM cable - 1131 | x | x | x |
| E59804411 | 40x40x20mm Maglev Fan 12V 6.3CFM 18dBA | | x | x |
| E57605811 | DR08011-A dust filter for DB6 | | x | x |
| E54700202 | Cable U.S.A. Black 3x18 AWG SVT 180 cm. | x | x | x |
| E54700102 | Cable EU Europe Black 3x0.75mm H05VV-F 180 cm | x | x | x |
| Remote | | | | |
| 712070066 | Service Clarity X Remote | x | x | x |
| Measurement Microphone | | | | |
| 7E59900111 | Measurement Microphone Clarity X AES | x | x | x |