Service Note		
Product	Description:	Service note no.
Remote CPU	Error to lock	SNo-T0147

Reason for note:

If a Remote CPU MKl is hooked up to a System 6000 MKll errors to sync up may occur

Actions:

The Remote CPU MKl must of course have software which works with the System 6000 MKll.

If still you encounter errors to sync up you have to ensure that the Compact flash card is at least $64\ MB$ in size.

IMPORTANT:

N/A