


Coordinates for each component are stated in the part list; see the column "Pos".

Pin numbers are shown in corners at large chips.

PCB layout, Main Board, PC13002-2, analog section



Coordinates for each component are stated in the part list; see column "Pos".

Pin numbers are shown in corners at large chips.