


Service Note		
Product	Description:	Service note no.
VoiceWorks	Micro controller change	SNo-T103

Reason for note:

Due to a change in micro controller we can not provide the “old” (big) type of micro controller any more. We can provide you with the “new” (small) type of micro controller. The difference is the size and the fact that the old fits into a socket. So please make sure you check which type you need before ordering this item.(see picture below).

Small is the new type.

Big is the old type.



Actions:

In case you need the old type you have to replace the complete board. Order no: 7B81021001.
 In case you need the new type you have to order item no: 7E49000230

IMPORTANT:

This replacement should only be carried out by skilled technicians.