

<b>Service Note</b>		
Products	Description:	Service note no.
<b>Play Electric</b>	<b>Product freezes</b>	<b>SNo-T210</b>


**Reason for note:**

Some customers have experienced issues with their Play Electric unit which freezes occasionally.

**Actions:**

Examinations have shown that some crystals are unstable and sometimes stop oscillation.

When a Play Electric product is in for service with these symptoms, please pay attention to the crystal X400 (located here).



A crystal from Abracon should be used for replacement. For a Music Group part number, please refer to the spare part list

**IMPORTANT:**

Please handle this as a standard repair