

Service Note		
Products	Description:	Service note no.
Voicelive Touch 2	Freezes – No boot	SNo-T215

Reason for note:

We have experienced some Voicelive Touch 2 products failing to boot up or freeze during normal use.

Actions:

Getting a Voicelive Touch 2 in for repair with these problems might be fixed by updating the firmware to the newest revision. Please find newest firmware on TCH Voicesupport.

IMPORTANT: N/A