

Service Note		
Product	Description:	Service note no.
VoiceLive	Micro controller change	SNo- T102

Reason for note:


Due to a change in micro controller we can not provide the "old" type (big) of micro controller any more.

We can provide you with the "new" type (small) of micro controller.

The difference is the size and the fact that the old fits into a socket, so please make sure you check witch type you need before ordering this item.(see picture below).

Small is the new type.

Big is the old type.



Actions:

In case you need the old type you must replace the complete board order item no: 7B81120002.

In case you need the new type you order item no: 7E49001501

IMPORTANT:

This replacement should only be carried out by skilled technicians.