

Service Note		
Product	Description:	Service note no.
D22	Pedal input mounting error	720 10 T021

**Problem:** Mounting error from factory R265 missing.

*Missing for serial numbers:*

2001931 – 2001950

1931-32-34-35-39-41-49

**Solution:** Mount the 10kohm SMD R265 if it is missing

